

## Menu


HISTORY FILE MAP for year 2007

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



288.13:27-17:05

1024 bps realtime TM degraded at DSS-65 due to TX (SBE2) problem at DSS-66 (DSS-65 does not have U/L capability in S-Band). Switched to SBE1. DR M104465 refers.